

# GIPRO DS-SERIES GEAR INDICATOR Supplementary Manual




## Honda CBR1000RR 2006-2007 (GPDT-H01)

Remove the left side middle fairing.



Connect the Gipro connector to the diagnostic system connector.

*(Red, 4-pole connector with red cap near the fusebox)*



Typical position for the gear indicator.

Secure the unit properly.

