

GIPRO DS-SERIES GEAR INDICATOR

Supplementary Manual



Honda CBF1000 F ABS 2010-2016 (GPDT-H01)

Secure the bike on a stand.




Remove the seats and the plastic cover from the right side.

Locate the diagnostic connector.

(Red, 3-pole connector)



Connect the Gipro connector to the diagnostic system connector.



GIPRO DS-SERIES GEAR INDICATOR

Supplementary Manual



Honda CBF1000 F ABS 2010-2016 (GPDT-H01)

Typical position for the Gear Indicator.

Secure the unit properly.

(Shown with the optional Gipro Mount, part no.: GIPRO-M-BK)

